

Freeze Check Thermolabels

Product Specifications

Response Temperature	0°C /32°F
Temperature Accuracy	+0°F/-2.7°F (+0°C/-1.5°C)
Size	1.125" x 2.375"
Characteristics	Irreversible color change from clear to white and the green check mark is no longer visible
Storage	Room temperature or below
Shelf Life	2 years, stored in a cool, dry place
Holster, Dual Purpose	Belt clip for carrying and insulation from thermal shock



Model 54000

The Freeze Check ThermoLabel is used to indicate an out of range temperature excursion below 32°F (0°C). When the temperature drops below the threshold, the indicator changes irreversibly from clear to white and the green check mark is no longer visible.

- **Indicates temperature abuse for products that are sensitive to lower limit temperature excursions.**
- **Adhesive labels can be applied to a product, package, carton or master pack.**
- **Tamperproof method for verifying when freeze damage has occurred during shipping, storage, or handling.**

DeltaTRAK manufactures products under an ISO 9000 registered quality management system

SS0105 13H1

